

South Tyneside Council

RISK ASSESSMENT

Department: Services for Young People, Children, Adults & Families		Section: Thurston	Assessment No: H2							
Work Activity	Minibus									
Method/Task	Risk rating, without controls (see Matrix overleaf)									
Hazards	Vehicle Roadworth Other Road Users Mechanical Break Passenger Difficul Passengers Emba Fire	-	High Medium Low							
	Employees:		Sub Contractors:	\boxtimes	Publi	c:				
Population Exposed	Young Persons:		Special Groups:	\boxtimes	Child	ren:				
Control Measures	Regular maintenance schedule & vehicle checks Driver vehicle checks (the driver is responsible by law for the condition of the vehicle – do not proceed if unroadworthy) As necessary journey planning includes road and weather reports Cancel journey if necessary Driver holds relevant qualification for driving minibus on their licence Current best practice is followed in respect of driving and rest hours Driver pays attention to relevant speed restrictions for vehicle and roads travelled Serviceable and in date fire extinguisher & first aid kit All passengers sit in seats with seat belts fastened at all times when vehicle in motion Exits must not be blocked with luggage or equipment Young people must not be allowed to move around the vehicle when it is in motion Staff supervision to ensure young people do not distract the driver									
Information Instruction Training Required	As above									
Personal Protective Measures										

Implementation Plan					Ву	Whom	Target Date	
Risk Rating	with	Controls in p	lace	HIGH		MEDIUM	LOW	
Monitoring and		Review Date				Whom	Target Date	
Review		ec 2020		Staff .		Jan 2022		
Action Identified From Review	No	one		By Whom		Target Date		
[Γ	Risk M				\neg	
			Worst Case	Outcome				
	70		Fatality Major Inj		ury Minor Injury		<u>/</u>	
	Likelihood	Probable	HIGH	HIGH		MED.		
	kelii	Possible	HIGH	MED		MED.		
	— Improvation		LOW		LOW			
Assessment conducted by: Signed: Revised: December 2020. AS, RC, JS.								