

South Tyneside Council

RISK ASSESSMENT

Department: Services for Young People, Children, Adults & Families		Section: Thurston	Assessment H9									
Work Activity	Tractor											
	Vehicle. Fit for pur Other site users. Mechanical failure).	Excessive/unbala Weather / Ground	Risk rating, without controls (see Matrix overleaf)								
Hazards	Hydraulic equipmond Log splitter Fire Lone working		High 🖂									
	Unauthorised use Changing of attac		Low									
Population Exposed	Employees:		Sub Contractors:		Publ	ic:						
	Young Persons:		Special Groups:		Chile	dren:						
Control Measures	Staff training, only used by staff who have received training Regular maintenance and scheduled vehicle checks Consideration given to when and how tractor is used Lone working only when appropriate Ensure tractor is locked and secured after use Log splitter only to be used by trained personnel Whenever possible use left hand door Consideration give to locking off hydraulic bucket when not in use Manual handling and safety best practise to be followed when changing attachments and refuelling Continue on separate sheet, if necessary											
Information Instruction Training Required	Only to be used by officially trained staff.											
Personal Protective Measures (PPE)												

Implementation Plan					By	Whom	Target Date		
Risk Rating with Controls in place						MEDIUM	☐ LOW		
Monitoring and Review		Review Date				Whom	Target Date		
IZGAIGAA	De	ec 2020					Jan 2022		
Action Identified From Review	No	one			Ву	Whom	Target Date		
			Risk N	Matrix	<u> </u>		<u> </u>		
	_	Worst Case Outcome							
	~		Fatality	Major Inj	ury	Minor Injury	y		
	Likelihood	Probable	HIGH	HIGH		MED.			
	(elik	Possible	HIGH	MED		MED.			
		Improbable	MED.	LOW		LOW			
Assessment conducted by:			S	signed:	Date:				
					Rev	ised: Decembe	r 2020. AS, RC, JS.		