

8th March 2025

To all members of our school community,

Important Update: RAAC Inspection update

I am writing to update you on the inspection that was carried out at our school this weekend to assess the presence of Reinforced Autoclaved Aerated Concrete (RAAC) in our school buildings.

Following a thorough assessment by qualified contractors, I am pleased to inform you that no RAAC has been detected on our premises. This means that our school remains safe and there are no structural concerns related to RAAC.

The safety and well-being of our pupils, staff, and visitors remain our top priority, and we will continue to monitor and maintain our buildings to the highest standards.

If you have any questions or concerns, please do not hesitate to contact us. Thank you for your continued support.

Kind regards.

Pax et Bonum.

Dr P.C. Doherty OBI

Headmaster

Main School Office:

Upper Site: Mornington Road, Woodford Green, Essex, IG8 0TP | Telephone: 020 8504-3419 Lower Site: Sydney Road, Woodford Green, Essex, IG8 0TB | Telephone: 020 8504-8946





